

## BUILDING SAFETY CERTIFICATE

No...062.....

Dated: 08/04/2026

It is certified that the existing building St John's Academy at kuari Buzurg, Hilalpur Chowk, Industrial Area, Hajipur, Vaishali, Bihar -844102 is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	05	-	-	-	-	-

The building is owned/occupied by St. John's Academy have complied with the building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Building Const Dept..... (Name of Department/ Govt.) on 08/04/2026..... (date of inspection) in the presence of Neeraj Kumar (principal) and that the building/premises is fit for occupancy for running school with effect from 08/04/2026 for a period of 01 year..... years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 08/04/2026 at Hajipur..... by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: Mahendra Pratap

Name: Mahendra pratap

Designation Assistant Engineer

Name & Address of Department/Office. Building Const Dept  
Hajipur